

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher



Photo No: 1 **Picture Direction: NE**

Description: View of concrete building floor slab (Bldg 1018) located in southwest corner of Subject Property.



Photo No: 2 **Picture Direction: NW**

Description: View of gravel drive and concrete building floor slab (Bldg 912) located in west side of Subject Property.



Photo No: 3 **Picture Direction: SW**

Description: View of concrete water tower foundation (Bldg 1117) located in southwest corner of Subject Property.



Photo No: 4 **Picture Direction: N**

Description: View of western Subject Property boundary area.

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher



Photo No: 5

Picture Direction: -

Description: View of likely abandoned in-place UST located in the northwestern portion of Subject Property - north of Bldg 924. (one steel-lined down hole about 2 to 3 ft in diameter, depth unknown filled with water)



Photo No: 6

Picture Direction: N

Description: View of likely abandoned in-place UST same as Photo 5, located about 70 feet east of the west AxleTech Building wall and north of former Bldg 924.



Photo No: 7

Picture Direction: S

Description: View of likely abandoned in-place Sump/UST located in northwestern portion of Subject Property, north of Bldg 924. (one brick-lined down hole about 4 to 5 ft in diameter, depth unknown, filled with water)



Photo No: 8

Picture Direction: N

Description: View of likely abandoned in-place UST same as Photo 7, located about 120 feet east of the west AxleTech Building wall and north of former Bldg 924.

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher



Photo No: 9 **Picture Direction:** SW

Description: View of gravel and grass covered area in the northern portion of the west half of Subject Property, beginning about Bldg 914 and westward.



Photo No: 10 **Picture Direction:** NE

Description: View of the gravel and concrete floor slab covered area in the northern portion of the east half of the Subject Property, beginning about Bldg 920.



Photo No: 11 **Picture Direction:** S

Description: View of northeast corner of Subject Property and eastern Subject Property boundary along South Morgan Street.





Photo No: 12 **Picture Direction:** SW

Description: View of Subject Property from the southwest corner of West 119th Street and South Morgan Street

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher

	
<p>Photo No: 13 Picture Direction: S</p>	<p>Photo No: 14 Picture Direction: W</p>
<p>Description: View of typical subsurface feature, filled with construction demolition debris. (Bldg 511 vault)</p>	<p>Description: View of concrete area of Bldg 1014 having 1 primer coat and 2 grey epoxy coats, which encapsulates TSCA regulated PCB-contaminated concrete. PCB-contaminated soils are also located in this area.</p>

	
<p>Photo No: 15 Picture Direction: N</p>	<p>Photo No: 16 Picture Direction: NE</p>
<p>Description: View of grey painted concrete area of Bldg 512. TSCA regulated PCB-contaminated concrete is encapsulated beneath. Area demarked by concrete blocks.</p>	<p>Description: View of grey painted concrete area of Bldg 512.</p>

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher



Photo No: 17 **Picture Direction:** E

Description: View of oil-stained concrete and former transformer pads located in Bldg 511. Previous collected PCB wipe samples identified this as PCB-containing and a TSCA regulated area.



Photo No: 18 **Picture Direction:** N

Description: View of oil-stained concrete and former transformer pads located in Bldg 511, north of Photo 17. Previous collected PCB wipe samples identified this as PCB-containing and a TSCA regulated area.



Photo No: 19 **Picture Direction:** SW

Description: View of concrete floor slab associated with Bldg 1018 – former Electromelt Foundry. Oil staining observed on concrete. Pondered liquids observed were water from previous rain event.



Photo No: 20 **Picture Direction:** SW

Description: View of typical subsurface feature located in Bldg 1018 and filled with construction demolition debris.

Client: Chicago Dept. of Fleet and Facility Management
Location: Ingersoll Products, 1000 West 120th Street, Chicago IL
Photograph Date: December 20, 2011

Project Number: 144607.01
Photographer: Trevor Hornbacher

	
<p>Photo No: 21 Picture Direction: NW</p>	<p>Photo No: 2 Picture Direction: NE</p>
<p>Description: View of concrete floor slab associated with Bldg either 1018A or 912 in the western portion of the Subject Property.</p>	<p>Description: View of northern adjacent property and West 119th Street.</p>
	
<p>Photo No: 23 Picture Direction: SW</p>	<p>Photo No: 24 Picture Direction: NE</p>
<p>Description: View of southern adjacent property and 120th Street</p>	<p>Description: View of Western adjacent property.</p>